



Replacement Parts for Carefusion Alaris Pumps



All parts listed below are manufactured by AIV Inc.

Part Description	AIV Part #	OEM Ref. #
LVP 8100 Door Latch	AL12957	147085-100/49000222
LVP 8100 Door Assembly with Cable Harness	AL12956	10360242
LVP 8100 Door Assembly w/o Cable Harness	AL13123	TC10006464/49000239
LVP 8100 Cable Harness	AL12927	TC10007928
LVP 8100 Rear Case Assembly	AL13736	10013325
POC 8015LS Front Case Assembly w/ Keypad	AL13315	TC10008335/8759
POC 8015LS Keypad	AL13314	N/A
POC 8015 Front Case Assembly w/ Keypad	AL13045	TC10006225/8580
POC 8015 Keypad	AL13041	N/A
Flat Rate Repair for 8100 LVP	FLRT8100	N/A
Fixed Rate Repair for 8100 LVP (parts extra)	RP8100	N/A
Fixed Rate Repair for Alaris 8015 (parts extra)	RPMEDLEY	N/A
PCA Handset Repair	REP148349000	N/A
Alaris-Compatible Power Cord	PC10775	148452-000
Refurbished 8100 LVP Pump Units	Alaris8100	N/A

877.266.6897 • aiv-inc.com



FM 86787

The manufacturers listed are the holders of their respective names and/or trademarks, and are not to be taken as an endorsement or affiliation with AIV, Inc.

585K